

	POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT		REGION	SITE NUMBER (to be assigned by HQ)
			6	TXD 026 595 959
<p>NOTE: This form is completed for each potential hazardous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.</p> <p>GENERAL INSTRUCTIONS: Complete Sections I and III through X as completely as possible before Section II (Preliminary Assessment). File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-335); 401 M St., SW; Washington, DC 20460.</p>				
I. SITE IDENTIFICATION				
A. SITE NAME		B. STREET (or other identifier)		
Gimble Salvage Co.		3201 Engleke		
C. CITY	D. STATE	E. ZIP CODE	F. COUNTY NAME	
Houston	TX	77003	Harris.	

TXD 026 595 959

A preliminary assessment form 2070-2 was not completed for this site. However, Documentation of Cleanup was submitted on 05/15/85 and includes information which would have been covered in a preliminary assessment of the site.

SUPERFUND
FILE

FEB 04 1993

REORGANIZED



9532957